




RHODE ISLAND  
DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

235 Promenade Street, Providence, RI 02908-5767

TDD 401-831-5508

5 March 1998

Mr. Philip Otis, P.E., Remedial Project Manager  
US Department of the Navy, Northern Division  
Code 18, Mail Stop #82  
10 Industrial Highway  
Lester, PA 19113-2090



RE: Contractor's Close-Out Report for Building 56  
NCBC Davisville, Rhode Island  
Submitted 26 February 1998, Dated 25 February 1998

Dear Mr. Otis;

The Rhode Island Department of Environmental Management, Office of Waste Management (RIDEM) has reviewed the above referenced document and comments are attached.

If you have any questions or require additional information please call me at (401) 222-2797 ext. 7138.

Sincerely,

Richard Gottlieb, P.E.  
Principal Sanitary Engineer

Attachment:

cc: W. Angell, DEM OWM  
C. Williams, EPA Region 1  
H. Cohen, RIEDC  
M. Cohen, ToNK  
W. Davis, CSO NCBC  
J. Shultz, EA Eng. ✓

LETTER1.RWG/RICHG

**RIDEM Comments For:**

**Contractor's Close-Out Report For  
Building 56  
Naval Construction Battalion Center  
Davisville, Rhode Island**

Submitted 26 February 1998, Dated 25 February 1998

**1. Figure 2, Building 56 Site Plan.**

This Figure should also delineate the areas from where lead and TPH contaminated soil were removed. In addition, sampling locations should be included in this Figure.

**2. Page 4, Table 6-1, Disposal Facilities, Disposal Technologies, and Quantities.**

The quantity listed for excavated soil is approximately 11.11 tons. The slip for Bardon Trimount, in Appendix D, shows that 31.11 tons of soil was taken to this facility. Please clarify how much soil was taken to Bardon Trimount.

**3. General Comment.**

Please include documentation that the Navy accepts this work.